



PRODUCT INFO

Stone Chip Repair System - VW (VAS 6083A)

Art.: 10.1450.9999.VW

Set

The Stone Chip Repair System - VW (VAS 6083A) is a unique set of products specially developed to repair stone chip damage to lacquered parts in an efficient and very professional manner.

Stone chip damage to the paintwork is caused by external influences. The damage is always caused by small stones. Thrown up by the wheels of the car in front, they often hit the front of the car at high speed. This results in tiny chips in the paintwork of relatively young vehicles. They are often white if they have not penetrated the base layer.

In many cases the Stone Chip Repair System - VW (VAS 6083A) makes that lacquered parts with stone chip damage do not have to be completely resprayed. With just a small investment in time and materials the damaged parts can be restored to perfect condition.

The Stone Chip Repair System - VW (VAS 6083A) comes complete in a durable plastic case. The system is very organized and completely autonomous; there is no need for energy from an external source.

- Professional system for repairing stone chip damage.
- Lacquered parts do not have to be re-sprayed.
- Very small investment in materials and time.
- Autonomous system.

